Weathertzerfon Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH3503Work Order Type: WeatherizationAudit Name: 13013SH3503

CLIENT INFORMATION

Client ID: 13013SH3503

<u>AGENCY INFORMATION</u>

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM

Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT 1923 1878 SQ. FT.

Client ID: 13013SH3503

DOE Weatherization Assistant Version 8.6.0 Page 1 of 5

REPLAC	MINDOMS #2 2 22 22							
REPLAC WINDO' REPLAC	WINDOW #24 CE WINDOW SILLS #2,3 CE FACING BETWEEN V CE BROKEN PANE WIN W) CE WINDOW UNITS #27	3,9,10,11(I WINDOW DOW #18 7, 28	#9&10	AND #10&		TORM		
REPLAC	CE WINDOW(ONLY) #29	y		Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Su	Infiltration Reduction	Each	1					
2 Labor	Infiltration Reduction	Each	1					
Other Detail								
				[Cub Tatal	
Field Notes:			Measur	e Sub Total: [] ,	Sub Total:	
Field Notes: Measure 2 Refr Comment 18 CU. F			Measur	Componen			l	Inspected
Measure 2 Refr Comment 18 CU. F	FT.			Componen Estimated	<u> </u>		Actual	
Measure 2 Refr Comment 18 CU. F		<i>Units</i> Each	Measur Qty 1	Componen		Qty	l	Inspected
Measure 2 Refr Comment 18 CU. F # Material / Labor 1 Refrigerators	FT. Description / Comment	Units	Qty	Componen Estimated	<u> </u>		Actual	
Measure 2 Refr Comment 18 CU. If Material / Labor Refrigerators	Pescription / Comment Refrigerator	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 2 Refr Comment 18 CU. If Material / Labor Refrigerators	Pescription / Comment Refrigerator	<i>Units</i> Each	Qty 1	Componen Estimated	<u> </u>		Actual	
Measure 2 Refr	Pescription / Comment Refrigerator	Units Each Each	Qty 1 1	Componen Estimated	<u> </u>	Qty	Actual	

Work Order Bid (ID)

Client ID: 13013SH3503

DOE Weatherization Assistant Version 8.6.0 Page 2 of 5

Measure 3 Floo Comment 1878 SQ				Componen	ts FD1		1	Inspected	
Comment 1070 00	ment 1878 SQ. F1. R-19 Estimated					Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1878						
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1878						
Other Detail									
			Measur	e Sub Total:] ,	Sub Total:		
Field Notes:									
Measure 4 CO	Monitor is Needed			Componen				Inspected	
Measure 4 CO N	2 CO MONITORS			Estimated			Actual		
Measure 4 CO N Comment INSTALI # Material / Labor	2 CO MONITORS Description / Comment	Units	Qty	-		Qty		Inspected Total	
Measure 4 CO N	2 CO MONITORS Description / Comment	Units Each	Qty 2	Estimated		Qty	Actual		
Measure 4 CO N Comment INSTALI # Material / Labor	2 CO MONITORS Description / Comment		_	Estimated		Qty	Actual		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety	_ 2 CO MONITORS Description / Comment CO monitor	Each	2	Estimated		Qty	Actual		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety 2 Labor	_ 2 CO MONITORS Description / Comment CO monitor	Each	2	Estimated		Qty	Actual		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety 2 Labor	_ 2 CO MONITORS Description / Comment CO monitor	Each	2	Estimated		Qty	Actual		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety 2 Labor	_ 2 CO MONITORS Description / Comment CO monitor	Each	2 2	Estimated			Actual		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety 2 Labor	_ 2 CO MONITORS Description / Comment CO monitor	Each	2 2	Estimated Unit Cost			Actual Unit Cost		
Measure 4 CO N Comment INSTALI # Material / Labor 1 Health and Safety 2 Labor Other Detail	_ 2 CO MONITORS Description / Comment CO monitor	Each	2 2	Estimated Unit Cost			Actual Unit Cost		

Measure 5 Fix A	Componen	ts		II.	nspected			
Comment REVEN	T W/H 15FT THROUGH	ROOF						
			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Measure 6 Prac (Wal	tice Lead Safe Weather Is)	rization		Componen				nspected
(Wal	ls)			Estimated	,	04:	Actual	
(Wal Comment # Material / Labor	ls) Description / Comment	Units	Qty	-		Qty		nspected
(Wal Comment # Material / Labor	ls) Description / Comment		Qty 1	Estimated	,	Qty	Actual	
(Wall Comment # Material / Labor 1 Health and Safety	ls) Description / Comment	Units		Estimated	,	Qty	Actual	
(Wall Comment # Material / Labor 1 Health and Safety	Description / Comment Equipment	<i>Units</i> Each	1	Estimated	,	Qty	Actual	
(Wall Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment Equipment	<i>Units</i> Each	1	Estimated	,	Qty	Actual	
(Wall Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment Equipment	<i>Units</i> Each	1	Estimated	,	Qty	Actual	
(Wall Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment Equipment	Units Each Each	1	Estimated	,		Actual	Total

Measure 7 Pres	sureRelief Piping Need	led		Componen	ts			Inspected
Comment ADD DR	OP ON T&P VALVE							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Pressure relief piping	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
-	or Barrier Needed			Componen	ts			Inspected
•	ement/CrawIspace) _ GROUND COVER TO	INCLUDE	E CRAV	WL SPACE	DOOR U	NIT (32	2	
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement / crawlspace vapor barrier	SqFt	1878					
2 Labor	Labor	Each	1878					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

Client ID: 13013SH3503